Flooding problem at Ruth Holmes' residence 2259 N. Higley Road Adjacent to AWCC 16th Hole



Ruth Holmes surveys the area behind her home on the 16th hole, which is subject to constant flooding during heavy rainstorms.



As seen in this photo the floodwater is unable to drain since the drain inlet is well above the level the water.



Flooding occurs during heavy rainstorms, saturating the ground and then disappears only through evaporation days later.



The drain outlet empties onto N. Higley Road, but does not serve its purpose since the floodwaters never reaches the drain inlet.



Run off from Nicklaus, Demaret and Floyd runs through this drainage ditch, across the 16th fairway and then collects.



Floodwater that collects and saturates the ground finds its way into the crawl space and takes many days to disappear.



During a heavy rain, water collects on N. Higley and floods the roadway, preventing some residents from getting their mail.



The storm drain located near the entrance to Rosburg Drive is a long way from the homeowners living in the distance.