

CONFIDENTIAL

MG Dealer

MG / 332

SERVICE MEMORANDUM

MGF / 56

18 October 1960

DISC BRAKE PADS

MGA Twin Cam

MGA 1600

Wear on these is automatically compensated during braking and manual adjustment is therefore not required.

However, to maintain peak braking efficiency and maximum pad life, the pads should be examined at every 3,000 miles (4,800 km.) service. Should the wear on one pad be greater than on the other, their operating positions should be changed over.

Workshop Manual, Driver's Handbook and Voucher Book references are being suitably amended.